

PROPELLER LOG BOOK



SENSEINICH PROPELLER MFG. CO.

Lititz, Pennsylvania 17543

Internet: <http://www.sensenich.com>.

THIS LOG BOOK IS TO BE KEPT
WITH THE PROPELLER
FOR RECORDING OF ALL PROPELLER MAINTENANCE WORK PERFORMED

PROPELLER MAINTENANCE RECORD

PROPELLER MODEL 70CM7S9-79
 PROPELLER SERIAL NUMBER 34753 K

TABLE OF PROPELLER ATTACHING BOLT WRENCH TORQUE
 Sensenich Metal Propellers (the proper torque is also shown on Blade Information Decal)

PROPELLER SERIES**	BOLT DIA. (inches)	RECOMMENDED WRENCH TORQUE		
		In.-lb.	ft.-lb.	n.-m.
69CK, M69CK (6 bolts)	3/8 (0.375)	280-300	20-25	32-34
72CK (6 bolts)				
74CK, M74CK (6 bolts)				
76AK, M76AK (6 bolts)				
76AM6, M76AM (6 bolts)				
74DM6, M74DM (6 bolts)				
74DR, M74DR (8 bolts)				
74DM7 (6 bolts)		480-540	40-45	54-61
72CC, 72FM8 (6 bolts)				
74DC, M74DC (6 bolts)				
76EM8, M76EMM (6 bolts)		320-380	60-65	81-88
* 80BM8, M80BMM (bolts)				

The subject aircraft was involved in an incident / accident on 9-5-20 rendering it total loss as not repairable within its insured value. For further information refer to file # 40225265
 Signed [Signature] Date 12/10/20
 Phoenix Aviation Managers, Inc.
 625 Highlands Blvd., Suite 108
 Coatesville, PA 19320

* Not in production

** These are the basic propeller models. Spacer addition does not affect recommended wrench torque.

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		9-22-04 Sensenich 70CM759-0-79, serial #34753K was overhauled, straightened, set pitch & track I/A/W service manual SPM590. The mechanic making the installation must comply with FAR 43.9.	
		Repair Station DM2R773K certifies this OTD is airworthy with respect to the work performed. San Antonio Propeller Service, Inc. Signed <i>[Signature]</i>	
10-6-12	<i>Inspected</i>	<i>Prop & Spinner</i> <i>Track 56.1 (low)</i>	<i>Checked OK</i>

SAN ANTONIO PROPELLER SERVICE, INC. SERVICEABLE PARTS TAG

Work Order 13845

Customer Order No. _____

Customer's Name Farm & Ranch Aerial Service

Part Name Propeller Part Mfg. Sensenich

Part No. 70CM759-0-79 Serial No. 34753K

Remarks Propeller was overhauled, straightened,
& set pitch & track I/A/W service manual #

SPRM590.

MAINTENANCE RELEASE

This stamped paper is an official document and shall be kept with the AIRCRAFT'S OFFICIAL HISTORICAL RECORDS. Work accomplished under the above listed work order number is on file at this agency. The above component was repaired and/or inspected in accordance with the current FEDERAL AVIATION REGULATION, ground functionally tested and approved for return to service subject to Flight Operational Test. The mechanic making the installation must CW FAR 43.9

Signed [Signature]

Date September 22, 2004

San Antonio Propeller Service, Inc.
234 W. Turbo, San Antonio, Texas 78216
FAA Approved Repair Station No. DM2R773K

TIVES,
RS,

SIGNATURE

Sensenich 70CM759-0-79,
was overhauled,
set pitch & track I/A/W
SPRM590. The mechanic
installation must comply

DM2R773K certifies this
worthy with respect to the
ed.

Propeller Service, Inc.
[Signature]

10-6-12 Inspected Prop & Spinners Checked OK
Track 56.1 (low)

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
Date	1/25/14		
T.T.I.S.			
Hobbs/TACH	100.5		
I certify that this		Propeller	
has been inspected in accordance with a		100 hr	
determined to be in airworthy condition.			

James S. Gardner, Jr.
A/P 002469529 I.A.

