

THE
adlogTM

**AIRCRAFT
MAINTENANCE
RECORDKEEPING
SYSTEM**

512-342-4452

**PROPELLER
MAINTENANCE
RECORDS**

SOUTHWEST AERO PARTS



"WE BUY AND SELL ANY TYPE AIRCRAFT PART"

1234 99th Street
Stinson Airport
San Antonio, TX 78214

Office (210) 932-1736
(210) 932-2385
Fax (210) 932-0213

NAME	JAMES H. or ROBERT G. BAILEY	PHONE	605-692-7231
ADDRESS	409 20th AVE.	FAX	
CITY, STATE, ZIP	BROOKINGS, SD 57006	DATE	2-24-98

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	2820/4112 HAMILTON SYANDARD BLADES		\$3500.00
	ck# 4360		\$500.00
		HAL DUE	\$3000.00

BUYER:

KEEP THIS SLIP FOR REFERENCE

SR 10 J3 -TOP (S) A 13

PROP: 6135A-6 OR 6135A-7 BLADES
HAM STAN 2B 20 HUB

STARTER ECLIPSE E-80

WHEELS 7:50 - 10
8:50 - 10 TIRES

10" SMOOTH TAILWHEEL

ENGINE R-680-E3A

28" TAKE OFF
2300 RPM

CONTINUOUS
28" 2200

AIR SPEED

LEVEL FLITE 155

DIVE 198

FLAPS 108

CG 90.6 ↔ 92.1

DATUM 42³/₈" FORWARD OF FIREWALL

PROPELLER MAINTENANCE RECORDS

Log No. _____

Aircraft Registration No. _____

Propeller Manufacturer Hamilton Standard

Hub Model 2B20-317

Blade Design No. 6135A-9

Hub Serial No. T30291

Blade Serial No's.

1. T65603

2. T65604

3. _____

4. _____

Pitch Range:

High _____ Low _____

Feather _____ Reverse _____

Governor Manufacturer _____

Model No. _____

Serial No. _____

Date installed on aircraft _____

Time Between Overhauls (TBO) _____ Hours

If used on multi-engine aircraft:

Right Left

Front Rear

(All applicable information must be filled in)



TECH PUBLICATIONS INC.

P.O. BOX 1178/FREEHOLD, N.J. 07728
(201) 462-5330

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME
9-20-91			

TOTALS brought forward from previous page

Prop s/n T30291 was overhauled this date. The mechanic making the installation must c/w FAR 43.9.

SAN ANTONIO PROPELLER SERVICE, INC.
234 W. TURBO DR.
SAN ANTONIO, TEXAS 78216
SAN ANTONIO PROPELLER SER., INC.
REPAIR STATION 2154
SIGNED: W.D. 10014

N50227 Hamilton Standard Propeller log entry s/n T30291 12 October, 2015 3.5 hours tach
I certify that this Propeller has been inspected as part of N50227's annual inspection and is found to be in an airworthy condition at this time. Dan Gilbert, A&P 3045130 IA Dan Gilbert

SAN ANTONIO PROPELLER SERVICE INC.

SERVICEABLE PARTS TAG

Work Order 10014

Customer Order No. _____

Customer's Name Southwest Aero Parts

Part Name Propeller Part Mfg. Hamilton Standard

Part No. 2B20-317 Serial No. T30291

Remarks Overhauled.

Inspector [Signature]

MAINTENANCE RELEASE

This stamped paper is an official document and shall be kept with the AIRCRAFT'S OFFICIAL HISTORICAL RECORDS. Work accomplished under the above listed work order number is on file at this agency. The above component was repaired and/or inspected in accordance with the current FEDERAL AVIATION REGULATION, ground functionally tested and approved for return to service subject to Flight Operational Test. The mechanic making the installation must C/W FAR, 43.9

Date 9-20-91

Signed [Signature] for

SAN ANTONIO PROPELLER SERVICE, INC.

234 W. TURBO, SAN ANTONIO, TEXAS

APPROVED REPAIR STATION NO. 2154

n 4-30-91
cut 9-20-91
Hamilton, TX
T30291
1 T65603
2 T65604
3 _____
4 _____

AUTHORIZED BY _____

Disassembly: DAVID

Hub & Blades: DAVID

Dome: DAVID

Pitch - Base -3° keep

Low 8.0°

High 19.0°

Rev N

Blade Rework - Angle of Band N

Location N

Blade Finish: Sets & Paint

Hub Rework: Sanded

[Signature]

Magniflux yes


Plated yes

[Signature]

Page No. _____

DATE	TOTAL TIME IN SERVICE	TOT TIM SIN(OVER)
9-20-91		

N50227 Hamilton Standard Propeller log entry s/n T30291 12 October, 2015 3.5 hours tach
I certify that this Propeller has been inspected as part of N50227's annual inspection and is found to be in an airworthy condition at this time. Dan Gilbert, A&P 3045130 IA Dan Gilbert

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
Propeller Log Entry 3-11-2017 Hamilton-Standard 2B20 S/N T30291 TT UNK TSMOH 43.7				
Cleaned and visually inspected Hub and blades.				
Greased Hub and counterweights with Aeroshell #5 grease.				
David Hanus A&P 2676877				
				

N50277 Stinson V-77 Hamilton Standard 2B20 S/N T30291





3-11-2017 Tach: 43.7 TSOH: 43.7 TTPROP: Unknown

Visual inspection of propeller hub and blades, OK. Dressed blades for minor nicks, serviced propeller as needed.

J.B. Ferrell A&P 3179543/A



				SUB-TOTALS this page
				TOTALS—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
Propeller Log Entry May 01-2018 Hamilton-Standard 2B20 S/N T30291 T.T. UNK TSMOH 85.3 Cleaned and visually inspected hub and blades. Greased hub and counterweights with Aeroshell #5 grease. David Hanus A&P 2676877 				
N50277 Stinson V-77 Hamilton Standard 2B20 S/N T30291 Tach: 85.3 TSMOH: 85.3 TTPROP: Unknown. Cleaned and visually inspected hub and blades, dressed minor nics in blades, greased hub and counter weights with AeroShell #5. J.B. Ferrell A&P 3179543 IA 				
4-10-2020				I certify that this <u>Propeller</u> has been inspected IAW a annual inspection and found to be in airworthy condition. Chuck Rautiola A&P 470542632 IA 
5-11-2021	142.0			I certify that this <u>Propeller</u> has been inspected IAW a annual inspection and found to be in airworthy condition. Chuck Rautiola A&P 470542632 IA 
				SUB-TOTALS this page
				TOTALS—Carry forward to next page

Tach Reads 118.1

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		✓		TOTALS brought forward from previous page
2-1-22	tach	154.7		C/w 100 inspection Checked for leaks and dressed blades Chuck Rautola A&P 470542632
3-1-23	tach	168.2		I certify that this <u>Propeller</u> has been inspected IAW a annual inspection and found to be in airworthy condition. Chuck Rautola A&P 470542632 IA Chuck Rautola
				SUB-TOTALS this page
				TOTALS—Carry forward to next page